



Velos 2019.1 SR3

SowSense

- Fixed an issue where the farm overview page and the animal overview page were not loaded correctly. This occurred in case a sow had a feed balance for a feed type that was not in her current feed plan. This could e.g. happen after moving the sow from the gestation area to the farrowing area.
- Fixed an issue that made it impossible to change the feed plan limits on mobile devices.

PorkSense

- Fixed an issue where the number of completed days for a pen was not always equal on the farm overview page and on the location overview page.

General

- Fixed an issue where the log page did not save the entire content of the log to a zip file.
- Fixed an issue where reports with Chinese characters were not downloaded correctly in Internet Explorer.
- Fixed an issue where saving a user without a first name showed an error. The first name is not a required field.

Velos 2019.1 SR2

ProSense

- Fixed an issue where in some cases the "refill not sufficient" system attention could occur too often.

General

- Disabling the buttons on the Rinstrum weighing indicator, to prevent accidental taring or zeroing, does not work correctly on older Rinstrum indicators with firmware version 3.15. Buttons will no longer be disabled on these devices.
- To ensure stable operation of our Velos system for customers worldwide, we are continually updating our software with added features, bug fixes and performance improvements. During regular improvements we encountered a security issue in Velos 2019.1-SR1. While this hasn't affected any installations we addressed this issue in 2019.1-SR2, the regular service release for Velos 2019.1.

Velos 2019.1 SR1

SowSense

- When switching on the calibration mode for farrowing feeding it would stay in the calibration mode forever if the calibration mode was not actively switched off by the user. Now the calibration mode will end automatically after 30 minutes in case the user forgets to do so. If more than 30 minutes is needed for calibrating then the calibration mode must be activated again after 30 minutes.
- Fixed an issue where newly calculated calibration values were displayed incorrectly with many digits.

PorkSense

- Improved selection of left/middle/right exit on the PorkTuner in situations when a pig is present in the selection gate area.
- Fixed an issue where, after changing the settings, the PorkTuner would not start-up again.

General

- To ensure stable operation of our Velos system for customers worldwide, we are continually updating our software with added features, bug fixes and performance improvements. During regular improvements we encountered a security issue in Velos 2019.1. While this hasn't affected

Release notes Velos 2019.1



any installations we addressed this issue in 2019.1-SR1, the regular service release for Velos 2019.1.

- Timezones database updated.
- Cannot change user settings.
- Time changes after reopening separation rule.
- Potential lockup when using wireless VPacks.